

<b>L Number</b>	<b>Hits</b>	<b>Search Text</b>	<b>DB</b>	<b>Time stamp</b>
<b>17</b>	<b>96516</b>	<b>"vehicle" and "cooling"</b>	<b>USPAT; US-PGPUB; EPO; JPO; DERWENT</b>	<b>2004/11/01 10:40</b>
<b>18</b>	<b>1376</b>	<b>("vehicle" and "cooling") and "trunk"</b>	<b>USPAT; US-PGPUB; EPO; JPO; DERWENT</b>	<b>2004/11/01 10:25</b>
<b>19</b>	<b>18</b>	<b>(("vehicle" and "cooling") and "trunk") and "discharge port"</b>	<b>USPAT; US-PGPUB; EPO; JPO; DERWENT</b>	<b>2004/11/01 10:45</b>
<b>20</b>	<b>17</b>	<b>("2294036"   "2667336"   "3455595"   "3595029"   "3656541"   "3817054"   "3908900"   "4252053"   "4324286"   "4376408"   "4612975"   "4996849"   "5054378"   "5167129"   "5325912"   "5902181"   "5904052").PN.</b>	<b>USPAT</b>	<b>2004/11/01 10:27</b>
<b>21</b>	<b>342</b>	<b>"vehicle" and "battery cooling"</b>	<b>USPAT; US-PGPUB; EPO; JPO; DERWENT</b>	<b>2004/11/01 10:40</b>
<b>22</b>	<b>12</b>	<b>("vehicle" and "battery cooling") and "trunk"</b>	<b>USPAT; US-PGPUB; EPO; JPO; DERWENT</b>	<b>2004/11/01 10:41</b>
<b>23</b>	<b>4</b>	<b>("3686530"   "5546862"   "5686884"   "5795182").PN.</b>	<b>USPAT</b>	<b>2004/11/01 10:43</b>